

## **Toshiba Satellite PSAW Series Laptop Service center in Hyderabad**

Posted by toshibaadmin - 18 Sep 2019 10:53

---

We offers all Kinds of computer peripherals chip level services. We are one of the leading motherboard chip level service centre in Hyderabad. We are servicing all kind of mother boards. We have been engaged in providing chip level service for many reputed clients across Hyderabad

### **Toshiba Laptop Service Center in Kukatpally**

No.210B, Vijaya Sai Tower,

Second Floor, Viveknagar

Kukatpally, Hydeabad - 500072

**Call: 040 48510111, 7997272463, 7997272205**

Landmark : (opp to BJP Office / Above Reliance Digital)

Email :

This e-mail address is being protected from spambots. You need JavaScript enabled to view it

### **Toshiba Laptop Service Center in Gachibowli**

Shop No 1 & 2, No 1-26/2 Basement Floor,

Gachibowli - Miyapur Road,

Gachibowli, Hyderabad

Telangana – 500032

**Reach Us : 7331133305, 7331133306, 7331133307**

Landmark: Opp Central Mall Behind TATA Motors

## **Toshiba Service Center - Toshiba Service Centre Contact Details**

Generated: 6 May, 2025, 10:22

---

Email :

This e-mail address is being protected from spambots. You need JavaScript enabled to view it

### **Toshiba Laptop Service Center in Madhapur**

No. 1-99/14, 3rd Floor,

Hitech City Road, Madhapur Main Road,

Hyderabad, Telangana 500081

**Reach us: 7331133301, 7331133302**

Landmark: opp Fortune Towers, Behind State Bank of India

Email:

This e-mail address is being protected from spambots. You need JavaScript enabled to view it

We offer these chip level motherboard services at competitive prices as compared to other service providers in the market. We render motherboard chip level services for laptops of all brands, having the following defaults:

### **Toshiba Laptop Service center in Hyderabad**

System dead.

No display.

System getting mute.

System getting hang.

Keyboard control section problem.

Memory control section problem.

Audio not working.

USB port not working.

Serial port not working.

CD Drive control section problem.

Hard disk control section problem.

Battery not charging.

=====